

Work Permit # <u>\$2005</u>— 05 \\
Work Order # ____ Activity# ____

. Work requester fills out	this section.	Standing Work Permit				
Requester: Tow L	10th Date: 2/14/6	os Ext.: 275	-3	Dept/Div/Group:	6/PHENIX	
Other Contact person (if diffe	ent from requester):	Marino		Ext.: 3704		
Work Control Coordinator:	Don Lynch	Start Date:	2/16/05	Est. End Date: 4//	1/05	
Brief Description of Work:	enove, Modity TREP	lace Power Supely	Modules	on Drift C	tamber on We	st Carriage
Building: 1008	Room: IR	Equipment: U	NA	Service Provider :	PHENIX	<i>-</i>
				_		
	e, Service Provider, and ES&H	(as necessary) fill out this section	on or attach analy	/sis		
ES&H ANALYSIS	<u> </u>				16-	
	None	Airbome	☐ Contan		Radiation	
	involved, notify Isotope Special N			nable materials involved,	notify Laboratory Critica	lity Officer
Safety Concerns	None	☐ Ergonomics		ort of Haz/Rad Material	T =	
Adding/Removing Walls or Roofs	☐ Confined Space*	Explosives	Lead*		Penetrating Fire Walls	
	☐ Corrosive	Flammable	☐ Magne		☐ Pressurized Sy	
Asbestos*	Cryogenic	Fumes/Mist/Dust*		al Handling	Rigging/Critica	
Beryllium*	Electrical	Heat/Cold Stress	☐ Noise*		☐ Toxic Materials	}"
Biohazard*	Elevated Work*	Hydraulic		nizing Radiation*	☐ Vacuum	· · · · · · · · · · · · · · · · · · ·
Chemicals*	Excavation	Lasers*		n Deficiency*	Other	
	ai clearance or surveillance from	the Occupational Medicine Clinic?				
Environmental Concerns	-1/ ^	None		mpacts Environmental Po		· · · · · · · · · · · · · · · · · ·
Atmospheric Discharges (Land Use		tivation/contamination	☐ Waste-Mixed	
Chemical or Rad Material	Storage or Use	Liquid Discharges	☐ Waste-		☐ Waste-Radioad	
Cesspools (UIC)	·	Oil/PCB Management	 =	Hazardous	☐ Waste-Regulate	
☐ High water/power consum	ption	Spill potential	☐ Waste-	Industrial	Underground D	uct/Piping
Waste disposition by:		3 4		· · · · · · · · · · · · · · · · · · ·	☐ Other	
	ste Minimization Opportunity:	X None ☐ Yes				
FACILITY CONCERNS	None			<u></u>		
Access/Egress	☐ Electrical Noise	Potential to Cause a False			☐ Vibrations	
Limitations	Impacts Facility Use Agr			rature Change	☐ Other	
Configuration Control	☐ Maintenance Work on V	entilation Systems	Utility I	nterruptions		
WORK CONTROLS						
Work Practices	T =	T			<u> </u>	
None	Exhaust Ventilation	Lockout/Tagout		ntainment	Security (see In	struction Sheet)
Back-up Person/Watch	☐ HP Coverage	Posting/Warning Signs	☐ Time Li	mitation	☐ Other	
☐ Barricades	☐ IH Survey	Scaffolding-requires inspection	☐ Warning	Alarm (i.e. "high level")		
Protective Equipment	_ <u></u>	1 inspection			Constitution of the second	
□ None	☐ Ear Plugs	Gloves	☐ Lab Coa	ot .	Safety Glasses	
☐ Coveralls	☐ Ear Muffs	Goggles	☐ Respira		Safety Harness	
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Co	,	Safety Shoes	☐ Other
	st be valid when job is scheduled			V*CI3	35 T S V 3 T T RC 3 S T R R R R R R R R R R R R R R R R R R	
None	Cutting/Welding	Impair Fire Protection Syste	me			
☐ Concrete/Masonry			3113			·
Penetration	☐ Digging/Core Drilling	Rad Work Permit-RWP No				
☐ Confined Space Entry	☐ Electrical Working Hot	Other				
Dosimetry/Monitoring				Alega .	A A A A A A A A A A A A A A A A A A A	
None	☐ Heat Stress Monitor	Real Time Monitor	☐ TLD			
☐ Air Effluent	Noise	Self-reading Pencil	☐ Waste C	haracterization		
	Survey/Dosimeter	Dosimeter	U Waste C			
Ground Water	☐ O ₂ /Combustible Gas	Self-reading Digital	☐ Other			
☐ Liquid Effluent	☐ Passive Vapor Monitor	Dosimeter Sorbent Tube/Filter Pump				
	elow specific training requirement		DENES	5 0 h	1100	
			The @ he		-W35	. 170 - N. G Avis by
	Walkdown Team determines th	e risk complexity and		permit when all hazard	rations are low only t	ne following need
coordination ratings below:		, , , , , , , , , , , , , , , , , , ,	to sign: (Alt	hough allowed, there is	s no need to use back	of form)
S&H Risk Level:	Low Moderate	☐ High	WCC:			Date:
-omplexity Level:	☐ Low ☐ Moderate	☐ High	Service Provi	der:		Date:
Work Coordination:	☐ Low ☐ Moderate	High	Authorization	to start		Date:
			(Departmenta	al Sup/WCC/Designee)	•	

	SEE ATTAC	MFD					
	SEE THIS	.,,,,,,					
Special Working Conditions Requi	red:						
3	No						
Operational Limits Imposed:							
Post Work Testing Required:	No		***				
Job Safety Analysis Required:		· · · · · · · · · · · · · · · · · · ·	Walkdown D	equired: Yes 🗹 No			
,	ies 🗾 iio		Walkdowit Ki	equiled. [] Tes [] No			
Reviewed by: Primary Reviewer that the hazards and risks that cou	will determine the size of the review ld impact ES&H have been identified	team and the other signal	gnatures required	I based on hazards and joi	b complexi	ty. Primary Reviewer signature me	
Title	Name (print)	Signature	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	Life#		Date	
Primary Reviewer	J-Sig TT	bock	100	/3/75	 	2/14/05	
ES&H Professional	P. Generalian	N.C.		21868		2/14/05	
Other	C PEARSON	Chear	<u></u>	15245		2/14/2005	
Gener Backup - Which	-						
Work Control Coordinator	D. Lynd	Listell	Jul.	20146		2/14/2005	
Service Provider							
	Review Done: in series	☐ team					
Hob Supervisor: Sall Workers: V. Paratugei	11/14 Life# P622	Life# P6221		Contractor Supervisor: Workers :		Life#:	
	R/11116	<i>,</i> ,					
V. Riaba	1) 697						
V. Riaba	1) 644.						
V. Riaba	1) 69 7						
V, Riaba	feedback on ES&H concerns or on i	deas for improved job	work flow. Use	feedback form or space be	elow.		
			work flow. Use	feedback form or space be	elow.		
5. Departmental Job Supervisor	feedback on ES&H concerns or on it Work Control Coordinator/Design ork: (Permit has been reviewed, wo	100			elow.		
5. Departmental Job Supervisor, Conditions are appropriate to start v	Work Control Coordinator/Design	100			elow.		
Departmental Job Supervisor, Conditions are appropriate to start v Name:	Work Control Coordinator/Design vork: (Permit has been reviewed, wo Signature:	nee ork controls are in place	e and site is rea	dy for job.)			
Departmental Job Supervisor, Conditions are appropriate to start where: Departmental Job Supervisor,	Work Control Coordinator/Design rork: (Permit has been reviewed; wo Signature: Work Requester/Designee determ	nee ork controls are in place	e and site is rea	dy for job.)			
5. Departmental Job Supervisor, Conditions are appropriate to start v Name: 6. Departmental Job Supervisor, Post Job Review (Fill in names of re	Work Control Coordinator/Design rork: (Permit has been reviewed; wo Signature: Work Requester/Designee determ	nee ork controls are in place	e and site is rea	dy for job.)	Date:		
5. Departmental Job Supervisor Conditions are appropriate to start v Name: 6. Departmental Job Supervisor, Post Job Review (Fill in names of re Name:	Work Control Coordinator/Design vork: (Permit has been reviewed, wo Signature: Work Requester/Designee determ viewers)	nee ork controls are in place	e and site is rea Life#. view is required	dy for job.)			
5. Departmental Job Supervisor Conditions are appropriate to start v Name: 6. Departmental Job Supervisor, Post Job Review (Fill in names of re Name:	Work Control Coordinator/Design vork: (Permit has been reviewed, wo Signature: Work Requester/Designee determination Viewers) Signature:	nee ork controls are in place	e and site is rea Life#: view is required Life#:	dy for job.)	Date:		
5. Departmental Job Supervisor, Conditions are appropriate to start viname: 6. Departmental Job Supervisor, Post Job Review (Fill in names of restame: Name: 7. Worker provides feedback. Norker Feedback (use attached she	Work Control Coordinator/Design vork: (Permit has been reviewed, wo Signature: Work Requester/Designee determ viewers) Signature: Signature:	nee ork controls are in place	e and site is rea Life#: view is required Life#:	dy for job.)	Date:		
5. Departmental Job Supervisor, Conditions are appropriate to start v Name: 6. Departmental Job Supervisor, Post Job Review (Fill in names of re Name: Name: Norker provides feedback. Vorker Feedback (use attached she	Work Control Coordinator/Design vork: (Permit has been reviewed, wo Signature: Work Requester/Designee determ viewers) Signature: Signature:	nee ork controls are in place	e and site is rea Life#: view is required Life#:	dy for job.)	Date:		
5. Departmental Job Supervisor, Conditions are appropriate to start where the start was a supervisor, Post Job Review (Fill in names of restance: Name: 7. Worker provides feedback. Norker Feedback (use attached sheet) WCM/WCC: Is any feedback required.	Work Control Coordinator/Design vork: (Permit has been reviewed, wo Signature: Work Requester/Designee determ viewers) Signature: Signature:	nee ork controls are in place nines if Post Job Rev	e and site is real Life#. view is required Life#: Life#:	dy for job.)	Date:		
5. Departmental Job Supervisor Conditions are appropriate to start v Name: 6. Departmental Job Supervisor, Post Job Review (Fill in names of re Name: Name: 7. Worker provides feedback. Norker Feedback (use attached she) WCM/WCC: Is any feedback req) Workers: Are there better method	Work Control Coordinator/Design rork: (Permit has been reviewed, wo Signature: Work Requester/Designee determ viewers) Signature: Signature: ets as necessary) uired?	nee rk controls are in place nines if Post Job Rev n the future? Yes	e and site is real Life#: view is required Life#: Life#:	dy for job.)	Date: Date: Date:		
5. Departmental Job Supervisor Conditions are appropriate to start volume: 6. Departmental Job Supervisor, Post Job Review (Fill in names of replame: Itame: 7. Worker provides feedback. Vorker Feedback (use attached she) WCM/WCC: Is any feedback required by Workers: Are there better method	Work Control Coordinator/Design rork: (Permit has been reviewed, wo Signature: Work Requester/Designee determ viewers) Signature: Signature: ets as necessary) uired?	nee rk controls are in place nines if Post Job Rev n the future? Yes	e and site is real Life#: view is required Life#: Life#:	dy for job.)	Date: Date: Date:	ptable condition. (WCC can	

Comments:

Drift Chamber repair in the PHENIX Experimental Hall (bldg. 1008).

Problem

The unmodified FEM power supply modules on the west Drift Chamber have been failing at an unacceptable rate. This is by now a well-understood problem. Modifications made to the modules on the east carriage, and to some earlier failed units on the west, have proven successful in preventing failures. The remaining modules on the west need to be modified. The intent is to trouble shoot these during an access period between now and April, 2005, and modify/replace them as appropriate.

Access to the installed location of the modules is difficult, as they are located 10 to 20 feet above track level, tucked inside the arc formed by the RICH detector, with the Central Magnet in front of the west carriage. The procedure developed below was used successfully in the past to remove quite a few failed modules.

Work Plan

This work is to be done by fully trained and experienced personnel during an access period. Access to the power supply modules is by extension ladders set up between the central magnet (CM) outrigger and the RICH vessel on the west carriage. For the higher modules, two ladders will be secured side-by-side, tied together, to allow climbing by the CM pole piece. All detectors in the IR will contain flammable gas during this operation. There is no access to the DC, PC, or TEC gas windows from the location of the ladders and no danger of damage to the gas volume from their installation. The Drift Chamber high and low voltage will be turned off. The 12-ton building crane will be positioned such to place the eye of a sling directly above the work area, then locked out. A harness will be worn and clipped to the sling while the work is being performed. A watch must be present at all times when someone is up on the ladders. All work in the IR will be supervised by Sal Marino.

Work will involve trouble shooting of the modules, and repair or replacement as appropriate.

- Ensure that power to the DC electronics is secured and that the CM power key is locked out of use.
- Erect and secure 1 (or 2 side by side if necessary) extension ladders between the top of the central magnet outrigger and the rich detector.
- Set up a tie off point just above the working position using the building crane and an adequately rated sling.
- The position of the tie off point is to be set for each working level and the crane must be locked out before the worker ascends the ladder.
- The worker is to use a body harness with a short clip-on lanyard and tie off before starting work.
- A watch must be present at all times when a person is on the ladders
- Remove or reinstall power supply modules as necessary.

